

Brochure-UniversalM50-5444.pdf  
COLREGS\_Navigation\_Rules.pdf  
EntechWest-EW4200Generator-OperatingManual.pdf  
HurthZF15RepairManual.pdf  
HurthZF-OilCompatibility.pdf  
KubotaengineTorqueValues-KubotaTractorCrossReferences.pdf  
KubotaModel-enginecrossReference.PDF  
KubotaServiceManual-V1902Engine-UniversalM5444.pdf  
KubotaV1902TorqueValues-EngineSpecifications.pdf  
MarchPump-LC-3CP-MC-Manual.pdf  
Mk-II-Gusher-10-.pdf  
OberdorferPump-N202M.pdf  
Perkins-WorkshopManual.pdf  
PerkoSwitichdiagram.pdf  
Universal\_Diesel\_Engine\_Data.pdf  
UniversalDiesel-KubotaPartsList-M5444-M50.pdf  
UniversalDiesel-OperatorsManualM12-M50.pdf  
UniversalDiesel-PartsList-M5444.pdf  
UniversalDiesel-ServiceManual5432-5444.pdf  
WalterVDrive-ExplodedDiagramRV26.pdf  
Westerbeke-BleedingProcedure-FactoryPublished.pdf  
Westerbeke-BleedingProcedure-UserModified.pdf  
WesterbekeBrochure.pdf  
westerbeke-Manual-4108OperatorsManual.pdf

Gearbox-Transmission\HurthTransmissionShopManual.pdf  
Gearbox-Transmission\OperatorManual-Paragon-P200P300P400.pdf  
Gearbox-Transmission\VelvetDriveSVCManual.pdf  
Gearbox-Transmission\WalterVDriveExplodedDiagramRV26.pdf  
Gearbox-Transmission\WalterVDrive-OpsMaintManual-RV10PearsonSpecial.pdf  
Gearbox-Transmission\WalterV-Drives-OpsMaintManual-DirectMountModelsRV10D-RV50D.pdf  
Modifications\AddingaTricolor-P367Seadragon.pdf  
Modifications\AddWinchtoBoom.pdf  
Modifications\CommissioningCheckList.PDF  
Modifications\Installation of Raymarine 6001 Linear Drive Autopilot.pdf  
Modifications\Installation-Raymarine6001LinearDriveAutopilot-P367SeaDragon.pdf  
Modifications\Installation-ShaftLok-P367Seadragon.pdf  
Modifications\Installation-ShowerGrate-CockpitTable-LeeCloths-GalleyBelt.pdf  
Modifications\InstrumentReplacements-DataMarine-P367Seadragon  
Modifications\InstrumentReplacements-DataMarine-P367Seadragon\DatamarineLX-360.pdf  
Modifications\InstrumentReplacements-DataMarine-P367Seadragon\DatamarineS100KL.pdf  
Modifications\InstrumentReplacements-DataMarine-P367Seadragon\DatamarineS200DL.pdf  
Modifications\InstrumentReplacements-DataMarine-P367Seadragon\Replacement-Instruments-P367Se  
Modifications\Maintenance-RebedPulpit.pdf

Modifications\Maintenance-ReplaceHeatExchangerZinc.pdf  
Modifications\Midshiptraveller\MidshipTraveler-Installation-P367SeaDragon.pdf  
Modifications\Midshiptraveller\MidshipTravelerInstallation-PartList.pdf  
Modifications\Midshiptraveller\MidshipTraveler-LoadCalculations-P367SeaDragon.pdf  
Modifications\RebeddingtheHatches.pdf  
Modifications\Replacement-CoachRoofPorts-NewFoundMetals.pdf  
Modifications\Replacement-TeakGrabRailsonDeck.pdf  
Modifications\Replacement-TheGudgeon-367.pdf  
Modifications\RiggingUpgrades\SlabReefing-Pearson367.gif  
Modifications\RiggingUpgrades\Upgrades-SeaFurlRollerFurlingandMainReefing-P367Seadragon.pdf  
Modifications\ScreenInstallation-DeckHatches.pdf  
Pearson-specific Documentation\365KetchDrawing.gif  
Pearson-specific Documentation\Dimensions-Icebox.pdf  
Pearson-specific Documentation\Factory Installed Equipment Options.gif  
Pearson-specific Documentation\LineDrawings-P367.gif  
Pearson-specific Documentation\Model Brochures\Brochure-Pearson365Ketch.pdf  
Pearson-specific Documentation\Model Brochures\Brochure-Pearson367.pdf  
Pearson-specific Documentation\Model Brochures\Brochure-Pearson36PH.pdf  
Pearson-specific Documentation\Model Specifications\Information-PearsonModelTimelines.gif  
Pearson-specific Documentation\Model Specifications\Specs-Pearson365Ketch.pdf  
Pearson-specific Documentation\Model Specifications\Specs-Pearson365PilotHouse.pdf  
Pearson-specific Documentation\Model Specifications\Specs-Pearson365Sloop.pdf  
Pearson-specific Documentation\Model Specifications\Specs-Pearson367.pdf  
Pearson-specific Documentation\OwnerManual-P356Ketch\OwnerManualP365Ketch-Pgs1-42.pdf  
Pearson-specific Documentation\OwnerManual-P356Ketch\OwnerManualP365Ketch-Pgs42-84.pdf  
Pearson-specific Documentation\OwnerManualP367.PDF  
Pearson-specific Documentation\PartsList1981P367.pdf  
Pearson-specific Documentation\Pearson36CutterSailPlan.pdf  
Pearson-specific Documentation\Pearson-Known365and367.pdf  
Pearson-specific Documentation\PearsonSerialNumbers.pdf  
Pearson-specific Documentation\RigTuning-BillShaw.pdf  
Pearson-specific Documentation\SlingLocation-P367.pdf

WesterbekeSVCB\Groups\Cooling-WaterHeater\Westerbeke-SVCBulletin-No107-ThermostatByPassHole  
WesterbekeSVCB\Groups\Cooling-WaterHeater\Westerbeke-SVCBulletin-No109-TwoPassEngineCooling  
WesterbekeSVCB\Groups\Cooling-WaterHeater\Westerbeke-SVCBulletin-No10-SeaWaterPumpAlignme  
WesterbekeSVCB\Groups\Cooling-WaterHeater\WesterbekeSVCBulletin-No114-WaterHeaterInstall-06N  
WesterbekeSVCB\Groups\Cooling-WaterHeater\Westerbeke-SVCBulletin-No72-GaugeSenderCompatibil  
WesterbekeSVCB\Groups\Cooling-WaterHeater\Westerbeke-SVCBulletin-No84-EngineOverheat-HxRubk  
WesterbekeSVCB\Groups\Cooling-WaterHeater\Westerbeke-SVCBulletin-No95-WaterHeaterInstallation

WesterbekeSVCB\Groups\Electrical\Westerbeke-SVCBulletin-No108-WireHarnessDiagramChanges-05M.  
WesterbekeSVCB\Groups\Electrical\WesterbekeSVCBulletin-No148-TachometerandHourMeterTroubles  
WesterbekeSVCB\Groups\Electrical\Westerbeke-SVCBulletin-No52-TestProcedure-DynaMonitor-02APR:  
WesterbekeSVCB\Groups\Electrical\Westerbeke-SVCBulletin-No82-StartBatteryRecommendation-19MA  
WesterbekeSVCB\Groups\Electrical\Westerbeke-SVCBulletin-No87-AlternatorOutputSplitter-18SEP1975  
WesterbekeSVCB\Groups\Electrical\Westerbeke-SVCBulletin-No92-TroubleShoot-WaterTempandOilPre:

WesterbekeSVCB\Groups\Exhaust\Westerbeke-SVCBulletin-No69-ExhaustFailure-WaterInjectionPoint-0  
WesterbekeSVCB\Groups\Exhaust\Westerbeke-SVCBulletin-No81-WaterLiftMufflerInstallation-03OCT19

WesterbekeSVCB\Groups\FuelSystem\Westerbeke-SVCBulletin-No11-ReplaceInjPumpDriveHubBushing-  
WesterbekeSVCB\Groups\FuelSystem\Westerbeke-SVCBulletin-No21-ReplaceInjectionPumpDriveHub-1!  
WesterbekeSVCB\Groups\FuelSystem\Westerbeke-SVCBulletin-No29-InjectionPumpHistory-June1969.p  
WesterbekeSVCB\Groups\FuelSystem\Westerbeke-SVCBulletin-No49-BleedingFuelSystem-27NOV1972.ç  
WesterbekeSVCB\Groups\FuelSystem\Westerbeke-SVCBulletin-No94-FuelPressureSwitchInstallation-09:

WesterbekeSVCB\Groups\gearbox\Westerbeke-SVCBulletin-No16-ParagonGearReductionIdentification-  
WesterbekeSVCB\Groups\gearbox\Westerbeke-SVCBulletin-No93-Paragon-AdjustP200SeriesReverseBar

WesterbekeSVCB\WesterbekeSVCBulletin-No132-SerialNumberCodes-08NOV1983.pdf  
WesterbekeSVCB\Westerbeke-SVCBulletin-No20-ConnectOilSensortoOilGallery-15JUN1969.pdf  
WesterbekeSVCB\Westerbeke-SVCBulletin-No29-GovernorSpringPosition-June1969.pdf  
WesterbekeSVCB\Westerbeke-SVCBulletin-No68-ReplacePistonRings-February1974.pdf  
WesterbekeSVCB\Westerbeke-SVCBulletin-No73-WrongDipstickShipped4-107-19JUN1974.pdf  
WesterbekeSVCB\Westerbeke-SVCBulletin-No80-LubCel-BetterColdStart-15MAR1975.pdf  
WesterbekeSVCB\WesterbekeSVCBulletins-All.pdf





Needed-01MAY1980.pdf  
-Descripton-05MAY1980.pdf  
nt-17SEP1976.pdf  
MAY1982.pdf  
lity-29MAY1974.pdf  
erEndcapMisalignment-04SEP1975.pdf  
-HoseRouting-07JUL1980.pdf

AY1980.pdf  
hooting-05JAN1985.pdf  
1973.pdf  
V1980.pdf  
i.pdf  
ssGauges-28APR1976.pdf

6MAY1974.pdf  
75.pdf

23APR1968.pdf  
5JUN1969.pdf  
df  
pdf  
SEP1976.pdf

03SEP1968.pdf  
rd-22JUN1976.pdf